

Z HARDWARE CO.

PO Box 1425
Brownwood, TX 76804
(800) 369-5970
Fax: (325) 646-1656
www.zhardware.com

MATERIAL SAFETY DATA SHEET

Z-Crackle Finish Step 1

Z-Crackle Finish Step 2

Z-Crackle Finish Step 1 Isopropyl Alcohol (cas# 67-63-0)

Z-Crackle Finish Step 2 Isopropyl Alcohol (cas# 67-63-0)

OSHA PEL: TWA 400 ppm ACGIH TLV: N/A

Other Limits: STEL500 ppm

Boiling Point: N/A Specific Gravity (H20=1) Z-Crackle Finish Step 1 - 1
Z-Crackle Finish Step 2 - 1.02

Melting Point: N/A

Vapor Pressure: N/A Vapor Density (A/R = 1) >1

Evaporation Rate (Butyl Acetate = 1) <1

Solubility in Water: Dilutable Flash Point (Method Used): N/A

Flammable Limits: N/A LEL: N/A UEL: N/A

Extinguishing Media: Dry chemical, CO2, water fog

Special Fire Fighting Procedures: N/A Unusual Fire and Explosion Hazards: N/A

Appearance and Odor: A viscous semi-transparent liquid with a mild acrylic odor.

REACTIVITY DATA: Stable Conditions to Avoid: N/A

Incompatibility: (Materials to Avoid): Strong acids and alkalis.

Hazardous Polymerization: Will not occur. Conditions to Avoid: N/A

HEALTH HAZARD DATA:

Routes of Entry: Inhalation: No. Skin: No. Ingestion: No.

Carcinogenicity: NTP: No. IARC Monographs: No. OSHA Regulated: No.

Signs and Symptoms of Exposure: Inhalation: No known symptoms associated with exposure to product. Skin & Eyes: No known symptoms associated with exposure to product. Ingestion: No known symptoms associated with exposure to product.

Medical Conditions Generally Aggravated by Exposure: N/A

Emergency and First Aid Procedures: **Inhalation:** Move subject to fresh air. Eye contact: Flush eyes with a large amount of water for at least 15 minutes. Skin Contact: Wash affected areas thoroughly with soap and water. Ingestion: If swallowed, give two glasses of water to drink. Consult a physician. Never give anything by mouth to an unconscious person.

